

Product change notification number:

PCN_202508027A_CANlink wireless 4001_4003 Update Firmware v3.1.0

Date: 27.08.2025**Title:** CANlink wireless 4001_4003 Update Firmware v3.1.0**Product identification:** See material number on type label.

Reason for change:

<input type="checkbox"/> Design	<input type="checkbox"/> Quality/Reliability	<input type="checkbox"/> Packaging
<input type="checkbox"/> Manufacturing Location	<input checked="" type="checkbox"/> Change of certification	<input type="checkbox"/> Labeling
<input type="checkbox"/> Expansion of product family	<input type="checkbox"/> Production Process	<input type="checkbox"/> Material
<input type="checkbox"/> Logistics	<input checked="" type="checkbox"/> Software update	<input type="checkbox"/> End of Life

Change Description:

- To ensure compliance with Radio Equipment Directive (RED) cybersecurity requirements, the CANlink wireless 4000 devices will be delivered with the new firmware version 3.1.0. In particular, this version will have stricter requirements when the device is configured as a Wi-Fi access point. The new firmware revision including the release notes is available for download in our [Download Center](#).
- The CANlink wireless 4000 devices will be delivered with a new bootloader version 2.0. This version will delete user configuration and all log data when the device firmware is updated locally over the CAN bus and the device is in bootloader mode (the Firmware Programmer will display a warning before executing an update operation that results in data deletion).
- For the CANlink wireless 4000 devices the Bluetooth Interface is disabled by default (except for Bridge-Sets).
- For the Bridge-Sets a unique Bluetooth Password was implemented.
- Proemion urgently recommends that you always update your devices to the latest released firmware version. Failure to update firmware may result in elevated errors for which Proemion is not obligated to provide technical support or warranty. If you have any problems or questions regarding the update, please contact our support team at <https://support.proemion.com>.
- Please check [Cyber Security - CANlink wireless 4000 Device Manual](#) for additional information.
- A new CE declaration of conformity will be issued and published at [Declaration of Conformity](#).

Identification method to distinguish the change:

Product Change Index printed on type label, see appendix. Firmware revision could be read out electronically.

Qualifiable impact on quality and reliability:

No impact on form and fit.

Samples: available will be available soon not applicable**Proposed first ship date¹:** 01.09.2025**Last time order for devices:** Not applicable**Last time ship for devices:** Not applicable**End of Repair-Service for devices:** Not applicable**End of Support for devices:** Not applicable**Proemion contact:** sales-team@proemion.com

¹ The proposed first ship date is the forecasted date that a customer may expect to receive changed products. This is determined by the estimated date of inventory depletion on the PCN issue date. This may be affected by fluctuations in supply and demand. Consequently, although customers should be prepared to receive changed products on this date, Proemion will continue to ship pre-changed products until a time in which the inventory has been depleted. This may result in pre-changed products being shipped to customers after this forecasted date.



Appendix

List of changed products

Proemion Part Number	Description	Product Change Index
253001072	CANlink wireless 4001	i05
253001073	CANlink wireless 4003	i05
253001193	CANlink wireless 4001 Bridge	i05
253001194	CANlink wireless 4003 Bridge	i05

